

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T--34-- NR--1--W--  
T 34 NR 1 E

----- Cheboygan ----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 24 & 19 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 8" W. Birch - S 87 W - 5 Links -----

8" Cedar - N 87 E - 109 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner was established, by proportionate measurement, by Forestry  
Division survey crew, while working in this area. Stumps all badly rotted, no  
positive identification.

Corner was placed and witnessed October 4, 1951.

SURVEYORS SEAL

SIGNED Sean C. DeLaMata DATE 12/5/51  
REGISTERED LAND SURVEYOR