

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 14 - 23

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED September 66

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

6" R. Pine N 55 E 36.9'

4" W. Pine S 28 E 39.0'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during survey in this area. Previously established by
Schaaf. Falls nearly midpoint on line between section corners.

SURVEYOR'S SEAL

SIGNED *Ronald J. Ostling* DATE 11-18-66
REGISTERED LAND SURVEYOR #10068