

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N.R. 3 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections  $\frac{25}{36}$

CORNER MONUMENT Left 1" iron pipe in place

DATE MONUMENT PLACED AND WITNESSED 4-14-67

WITNESSES TO CORNER.....



9" Cedar S 49° E 62.5'

12" Elm N 51° W 45.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making survey in this area. In approximate center of E-W road. Fence line N & S.

SURVEYOR'S SEAL

SIGNED \_\_\_\_\_ DATE 5-25-67  
REGISTERED LAND SURVEYOR #10068