

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Cheboygan
(County)

Located In

Corner Code #

1. Public Land Survey T 34N R 3W L9
T 34N R 3W L10
2. Property Controlling in Section S T R
S T R
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on March 20, 2002 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

L-9 G.L.O. Harvey Mellen 1855, Set quarter section post.

Wit: Cedar 12" North 80 links

Hemlock 10 S18°W 33 links

Orlando Doyle P.E. R.L.S. #7319, no date, Set 1" pipe

Wit: 5" Elm in Clump S59°W 94.00'

12" Poplar S13.5°W 32.30'

Orlando Doyle P.E. R.L.S. #7319, 1973, Found 3/4" pipe

Wit: 5" Poplar N25°W 8.25'

4" Poplar S32.5°W 17.32'

12" Poplar S23°15'E 31.94'

Brian K. Fulford P.S. #41099, August 1997, Cert. of survey

L. 678, P. 545 shows concrete monument recovered.

Wit: Willow clump N08°E 50.30'

1/2" Iron East 33'

7" Spruce S32°W 53.50'

Fence post West 17.35'

L-10 Kenneth J. Ostling R.L.S. #10068 set a 1" X 24" pipe at the intersection of the 1/4 lines.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

L-9 Found concrete monument with 1/2" bar.

L-10 Found 1" pipe fitting Kenneth J. Ostling Survey in section 25.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9 Concrete monument with 1/2" bar.

Wit: 4" Spruce S35°W 98.71'

4" Elm S62°W 80.32'

16" Elm S75°W 109.25'

8" Willow Clump N10°E 53.25'

L-10 Found 1" pipe

Wit: 6" Spruce

N14°E 27.17'

5" Elm

N75°W 21.13'

12" Maple

South 59.67'

12" Maple

S62°E 58.25'

Carsonite Post

North 1±

Signed by:

Carl T. Kiiskila

Date:

6-26-02

Surveyor's Michigan License No.:

33981

