

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Cheboygan  
(County)

Located In

Corner Code #

1. Public Land Survey	T	35N	R	1E	H-8
	T	35N	R	1E	I-8
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on March 30, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

H-8 – Center ¼ corner of Section 22, T35N, R01E

I-8 – ¼ Corner comm. to sec.'s 22 & 23, T35N, R01E

1975 – Certificate of Survey – L.359, p.296 – Delmer E. Porter, P.S.#15410 – Set ½"x 24" capped iron rod w/ cap#15410. Fence 9.5' West and 30.6' North.

1840 – GLO – Brevort- Set qr. Section post.  
Beech 12 N78°E 54  
Beech 16 N57°W 58  
1975 – L.C.R.C. – L.1, p.165 – Delmer E. Porter, P.S.#15410  
Fd. old 4"x 4" cedar post at Fe. corner. Set ½" rod and cap.  
N12°W 13.98' 5" Maple  
N75°E 7.41' 4" Maple  
S80°W 19.7' 4" Maple

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

H-8 – Center ¼ corner of Section 22, T35N, R01E

I-8 – ¼ Corner comm. to sec.'s 22 & 23, T35N, R01E

Found ½"x24" CIR#15410 per certificate of survey by Porter in 1975. The ½" rod fits the standard procedure for subdivision of a section. Replaced found CIR with stamped 2" dia. aluminum cap on 5/8"x 34" rebar. Found no other evidence to dispute the location for the corner.

Found ½" x 18" CIR#15410 at intersection of E-W and S fence lines per L.C.R.C. – L.1, p.165. Accepted found ½" CIR as the best available evidence for the position of the corner. Replaced ½" CIR with a standard DNR monument. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-8 – Center ¼ corner of Section 22, T35N, R01E

I-8 – ¼ Corner comm. to sec.'s 22 & 23, T35N, R01E

2" dia. stamped aluminum cap on 5/8"x 34" rebar.

4" dia. stamped aluminum cap on 1"x 36" galvanized pipe.

Wit: N44°E 14.18' to set N&T on NW side 4" Ash  
S16°E 33.71' to set N&T on SW side 5" S. Maple  
S63°W 13.30' to set N&T on SE side 6" Ash  
N60°W 27.22' to set N&T on N side 3" B. Fir  
N14°W 34' to Fence Corner N&E  
Set Blue Carsonite Post w/location tag 1' North

Wit: \*N70°E 7.38' to set N&T on S side 10" R. Maple Clump  
S29°E 13.22' to set N&T on E side 5" Oak  
S74°W 18.92' to set N&T on N side 4" S. Maple  
N16°W 3.60' to set N&T on E side 8" R. Maple  
South 0.50' to fence corner running N-S, E-W  
Set Blue Carsonite Post 1' North  
\* Witness of previous record.

Signed by:

Carl T. Kiiskila

Date:

5-1-12

Surveyor's Michigan License No.:

33981

