

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Cheboygan
(County)

Located In

Corner Code #

1. Public Land Survey	T		R		
	T		R		
2. Property Controlling in Section	S 22	T 35N	R 01E	3	
	S 22	T 35N	R 01E	4	
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on April 13, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

3 - N 1/16 Corner comm. to sec.'s 21 & 22, T35N, R01E

4 - NW 1/16 Corner section 22, T35N, R01E

None

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

3 - N 1/16 Corner comm. to sec.'s 21 & 22, T35N, R01E

4 - NW 1/16 Corner section 22, T35N, R01E

Set stamped 2" dia. aluminum cap on 5/8" x 34" rebar per standard BLM procedure. Corner falls 4' West of N-S centerline dirt road. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. aluminum cap on 5/8" x 34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3 - N 1/16 Corner comm. to sec.'s 21 & 22, T35N, R01E

4 - NW 1/16 Corner section 22, T35N, R01E

2" dia. stamped aluminum cap on 5/8" x 34" rebar

2" dia. stamped aluminum cap on 5/8" x 34" rebar

Wit: N26°E 82.00' to set N&T on SE side 5" R. Pine
N70°E 29.61' to set N&T on S side 22" W. Pine
S42°E 55.54' to set N&T on SW side 10" W. Pine
S08°W 59.83' to set N&T on W side 5" W. Pine
Set Blue Carsonite post w/ location tag 20' East

Wit: N28°E 53.13' to set N&T on W side 10" R. Oak
S55°E 30.15' to set N&T on NE side 6" W. Pine
S30°W 46.97' to set N&T on W side 14" R. Pine
N73°W 62.00' to set N&T on S side 8" R. Pine
Set Blue Carsonite Post w/ location tag 1' North

Signed by:

Carl T. Kiiskila

Date:

5-1-12

Surveyor's Michigan License No.:

33981

