LAND CORNER RECORDATION CERTIFICATE

| | | FIII | ing Require | ment of Act 74, K | //ich. PA 1970 | |
|--|--|--|---|--|---|-------------------|
| For Corners In: Cheboygan (County) | | Located | l In | Corner Code # | | |
| 1. Public Land Survey | | T | R | | | |
| Property Controlling in Section | | T 35N | R 01E | 10 | | |
| Miscellaneous Property in Section | s | т —— | R | - | Register of Deeds Stamp & File Nu | mber |
| 4. Lot No: | Recorded | Plat: | | | • | |
| | 110001000 | | | | A B C D E F G H I J K | L M |
| 5. Private Claims: | | | | | 2 - 6 - 5 - 4 - 3 - 2 3 | |
| I, Carl T. Kiiskila, in a fiel requirements of PA 74, Mi and 2 above were in conforthe current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established | chigan PA of ormance with a rvey instruction anagement or lines 3, 4 and f Land Surve | 1970, the coregulations at the Lorentz by a decree of 5 above we eyers or by | orner points mand rules there Inited States of a Court of lere in conform a Decree of | entioned in lines 1 efore as required in Department of the Law and/or that the lance with the rules f a Court of Law; | 5 6 -18 -17 -16 -15 -14 -7 7 6 -19 -20 -21 -22 -23 -9 | 112 |
| NOTE: Not more than be recorded on this ce | | all in the s | ame town ar | nd range, may | 10 30 29 28 26 | 25 |
| se resonate on any ce | i imouto. | | | | 11 12 31 32 33 34 35 | 36 |
| A. Description of origina | l monument | and acces | sories and/or | r subsequent restor | ration: | |
| 10 – S 1/16 Corner com | | | | , | | |
| None | | | , | | | |
| | | | | | | |
| | | | | | | |
| | | | | | <i>X</i> : | |
| | | | | | | |
| B. Description of corner 10 – S 1/16 Corner com | | | | ~ | re-establishing corner: | |
| | | | | | anna dian Carra falla di Marti (A) O | |
| Set stamped 2" dia. aluminum cap on 5/8" x 34" rebar per standard BLM procedure. Corner falls 1' West of N-S centerline dirt road. Found no other evidence to dispute the location for the corner. | | | | | | |
| | | | | | | |
| | | | | | | |
| C. Description of monun | nent for corn | ner and acc | essories esta | ablished to perpetu | ate locating the position of the corner: | |
| 10 - S 1/16 Corner com | mon to secti | ions 21 & 2 | 2, T35N, R0 | 1E | | |
| 2" dia. stamped alun | ninum cap o | n 5/8" x 34 | " rebar | | | |
| Wit: N47°E 44.60' to S60°E 42.90' to S69°W 42.25' to N47°W 39.80' to Set Blue Carsoni | set N&T on set N&T on set N&T on | SW side 11 N side 10" NE side 8' | I" R. Oak 'W. Pine ' Oak | | | |
| | | | | | | 23 |
| Signed by: | arl T | - Ni | als 0 | Date: _ | 5-1-12 | |
| Surveyor's Michigan | | / - | 3981 | | | MICHIN |
| | | _ | | | Section Co. | RL |
| | | | | | A KIIS | CILA & |
| | | | | | SURV | ND. EYOR |
| | | | | | No. 339 | 81 . 8 |
| EARM ARREDOVED BY MICHIGAN STATE BOARD OF SECTIONAL STATE BOARD OF SECTION STATE STATE BOARD OF SECTION STATE SECTION SECTION STATE SECTION SECTION STATE SECTION STATE SECTION S | | | | | | |
| FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS 19N1 28 1971 Revised May 14, 1975 Revised Jan. 1983 | | | | | | |
| | | | | | | Revised Oct. 1995 |