LAND CORNER RECORDATION CERTIFICATE

		Filing Requi	rement of Ac	t /4, Mich.	. PA 1970				
For Corners In: Cheboygan (County)	Loc	cated in	Corner Cod	e#					
1. Public Land Survey	<u> </u>	R							
Property Controlling in Section	S 10 T 3	5N R 01E 5N R 01E	1 9	_					
Miscellaneous Property in Section		R R		<u> </u>	Re	egister of D	eeds Stamp	& File Numbe	er
4. Lot No:	Recorded Plat:				A B C	CDE	FGHI	JKL	м
5. Private Claims:					2 6	6	4 - 3	-21-	٦
I, Carl T. Kiiskila, in a fie requirements of PA 74, Mi and 2 above were in confo the current manual of sur Interior, Bureau of Land Macorner points mentioned in of the Michigan Board o established, re-established NOTE: Not more than be recorded on this ce	chigan PA of 1970, imance with regulatively instructions of anagement or by a dines 3, 4 and 5 about 1 about 1 and 5 about 1 and 5 about 1 abo	the corner points ions and rules the the United State ecree of a Court ove were in confoor by a Decree vered, found as e	mentioned in li- erefore as requi- es Department of Law and/or the rmance with the of a Court of xpressed below	ines 1 ired in of the eat the rules Law;	3		10 15 15 15 15 15 15 15 15 15 15 15 15 15	-11 12 13 13 13 141413 13 14 15	
A. Description of origina	l monument and a	ccessories and	or subsequer	it restoration	n:				
<u>1</u> – W 1/16 Corner comr	m. to sec.'s 3 & 10	, T35N, R01E	<u>g</u>	- CE 1/16	Corner sect	tion 10, T3	35N, R01E		
1991 – Certificate of Survey – Sur. No.42-91 – Delmer E. Porter, P.S. #15410 – Found concrete monument.				Plat of Black Lake Shores Subdivision – L.526, p.461 473 – James H. Granger, P.S. #16041 – Shows setti concrete monument at corner position. References					
1998 – Certificate of Porter, P.S. #15	5410 – Found con				002, p.94.				
B. Description of corner	evidence found a	nd/or method ar	oplies in restor	ina or re-es	stablishing c	orner:			
1 – W 1/16 Corner comr					Corner sec		35N, R01E		
Found and accepte #15410 as the best corner. Found no other corner.	t available evidend	ce for the position	on of the	evidend cap #3	and accepte ce for the po 3981 on mo the location	osition of the	ne corner. Found no o	Placed 1/2" p	plastic P.S
C. Description of monur	nent for corner an	d accessories e	stablished to	oerpetuate l	ocating the	position of	f the corner	•	
<u>1</u> – W 1/16 Corner com	m. to sec.'s 3 & 10), T35N, R01E		9 - CE 1/1	6 Corner se	ction 10, T	35N, R01E		
4" dia. conc. monum	nent w/ P.S. cap #	15410		4" dia. con	c. monumer	nt w/ P.S. o	cap #33981		
\$50°W 23.62' to N37°W 42.78' to	set N&T on NE si set N&T on E side set N&T on SE si set N&T on N sid ite post w/ location	e 12" R. Pine ide 12" R. Pine le 10" Oak		\$10° \$59° N37° Drov	°E 35.29' to °E 25.00' to °W 12.04' to °W 13.30' to re 2" dia. x 5 Blue Carson	set N&T of set N&T of set N&T of long galv	on E side 5 on N side 3 on W side /anized pip	" Oak 3" Oak 5" J. Pine e South 1'	e:
Signed by:	and TR	us B 2		Date:	ر سے	-/2	JAS STAIL	CARL	44
Surveyor's Michigan		33981			5-1	-/_	31	LAND URVEYOR	*
			FORM APPROVE	ED BY MICHIG	AN STATE BO	ARD OF PRO	OFE SCHOOL OF	33981 SURVEYORS	JAN. 28, 19 FMay 14, 19

JAN. 28, 1971 viseo May 14, 1975 Revised Jan. 1983 Revised Oct. 1995