LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Cheboygan (County)		Located In		Corner Code #	
1. Public Land Survey		T 35N		G-7 G-8	
Property Controlling in Section	s	_ T	R		
Miscellaneous Property in Section	s	_ T	R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:				
5. Private Claims: _					2 6 6 1 1
1, Carl T. Kiiskila, in a fiel requirements of PA 74, Mi and 2 above were in confethe current manual of su Interior, Bureau of Land Mi corner points mentioned in of the Michigan Board of established, re-established	chigan Parmance vervey instrangement innes 3, 4 ff Land	A of 1970, the vith regulation uctions of the or by a decident of the condition of the cond	e corner point ns and rules th e United Stat tree of a Court e were in confe by a Decree	s mentioned in lines 1 herefore as required in less Department of the of Law and/or that the formance with the rules of a Court of Law;	3 4 - 7 - 8 - 9 - 10 - 11 - 12 - 13 - 15 - 14 - 13 - 17 - 161514 - 13 - 17 - 18192021222324 - 9
NOTE: Not more than	2 corne	re all in th	a cama towi	and range may	10 30 39 39 37 36 25

A. Description of original monument and accessories and/or subsequent restoration:

G-7 - Section Corner comm. to sec.'s 15,16,21,22, T35N, R01E

G-8 - 1/4 Corner comm. to sec.'s 21 & 22, T35N, R01E

1840 - GLO - Brevort- Set post cor. of sects. 15,16,21 & 22

Sp. Pine 7 S11 ½ °W 38 Sp. Pine 6 N38 ½ °E 24

1975 - L.C.R.C. - L.1, p.165 - Delmer E. Porter, P.S.#15410 - Fd.

3" pipe buried in trail intersection. N40°E 32.67' 6" J. Pine N43°W 40.27' 8" Oak S52°W 61.57' 10" J. Pine

be recorded on this certificate.

1840 - GLO - Brevort- Set qr. Section post. Beech 8 N681/2 °E 11 Ironwood 4 S68°W 14

1975 - L.C.R.C. - L.1, p.167 - Delmer E. Porter, P.S.#15410 - Set 1/2" rod by single proportion in West edge of trail.

N75°W 6.12' 8" Maple S37°W 15.06' 10" Birch \$40°E 64.99' 10" Lynn

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

<u>G-7</u> – Section Corner comm. to sec.'s 15,16,21,22, T35N, R01E

G-8 - 1/4 Corner comm. to sec.'s 21 & 22, T35N, R01E

Found and accepted 3" dia. pipe in trail road intersection as the best available evidence for the position of the original corner. Drove 60D spike in center of found pipe. Found no other evidence to dispute the location for the corner.

Found 1/2" x 24" CIR#15410 on W. edge of N-S trail road per L.C.R.C., L.1, p.167. Accepted found iron as a faithful and careful reestablishment of the position of the original corner. Replaced found 1/2" CIR#15410 with a standard DNR monument. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-7 - Section Corner comm. to sec.'s 15,16,21,22, T35N, R01E

G-8 - 1/4 Corner comm. to sec.'s 21 & 22, T35N, R01E

3" diameter pipe w/ 60D spike in center.

4" dia. stamped aluminum cap on 1"x 36" galvanized pipe.

Wit: *N66°E 51.57' to set N&T on NW side 10" J. Pine S64°E 44.71' to set N&T on NE side 12" R. Pine *S17°W 76.77' to set N&T on E side 16" R. Pine N45°W 57.96' to set N&T on NE side 9" R. Pine

Wit: N29°E 66.76' to set N&T on E side 13" W. Pine *S27°E 64.83' to set N&T on NE side 16" Basswood S67°W 42.25' to set N&T on SE side 10" W. Pine

N51°W 39.76' to set N&T on N side 14" Oak

* Witness of previous record.

* Witness of previous record.

MICHIGAN CARL LAND RVEYOR No. 33981

Surveyor's Michigan License No.:

33981

SCENSED W FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS

EYORS JAN-28, 1971 Revised May 14, 1975 Revised Oct. 1995