

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 36 NR. 1 E.

Cheboygan COUNTY

DESCRIPTION OF CORNER West 1/8 corner common to Sections 2 and 11

DESCRIPTION OF CORNER MONUMENT 3"x24" pipe, below surface

WITNESSES TO CORNER

BT 14" B. Oak - N73E - 21.8 feet

BT 7" J. Pine - S10E - 16.3 feet

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was established by Forestry Division survey crew while making a survey of Section 2. Moved a 3" pipe from fireline intersection to its corrected position at midpoint, on line between section and 1/4 corners. Pipe obviously not corrected to true position in previous survey.

Corner was placed and witnessed May 26, 1960.

SURVEYORS SEAL

SIGNED *Kenneth J. Ostling* DATE 6/9/60
REGISTERED LAND SURVEYOR