

# SURVEY & REMONUMENTATION

MAY 03 1995

## CHEBOYGAN COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

DEC 29 1994

### COMMISSION

For corners in

Cheboygan

(County)

Located In:

Corner Code #

1. Public Land Survey

T 36N R 1W

A-11

T R

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECEIVED FOR RECORD

at 12:44 O'clock P M

*Joanne Spraf*

CLERK/REGISTER  
CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

I, Richard C. Dunn, in a field survey on October, 19 94

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. John Mullett 1840  
Set Wood Post  
14" Pine S10°W 57 Links  
8" Aspen N39°E 37 Links

Kenneth Larson #10695, Mar. 1965  
Liber B, page 34  
Set 1" pipe w/4" DNR Brass Cap  
20" R. Pine S43°E 36.1'  
7" J. Pine S64°W 17.8'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-11 Fnd. 1" Pipe w/4" DNR Brass Cap per Kenneth Larson survey, Liber B, Page 34, Cheboygan County Records

*Monica P. Reed*

DEC 27 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11 Fnd. 1" Pipe w/4" DNR Brass Cap per Liber B, Page 34 and is accepted as a careful and faithful reestablishment of the position of the original corner.  
12" J. Pine N74°E 57.05'  
8" Aspen N55°W 9.00'  
8" R. Pine S37°W 68.43'  
8" Maple S42°E 74.95'

LIBER 010 PAGE 92

igned by

*Richard C. Dunn*

Date December 15, 1994

Surveyor's Michigan License No. 12020