

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Cheboygan

Located In

Corner Code #

(County)

1. Public Land Survey	T	37N	R	1E	C-5
	T	37N	R	1E	C-7
2. Property Controlling in Section	S		T		
	S		T		
3. Miscellaneous Property in Section	S		T		
	S		T		

Register of Deeds Stamp & File Number

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on October 31, 2001 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

C-5 G.L.O. George H. Cannon D.S. 1854
Set post corner of section 7,8,17,and 18
Wit: Yellow Pine 15 S40°E 45 links
Yellow Pine 12 N25°W 43 links

The Michigan Department of conservation re-established this corner by double proportionate measurement between section corners one mile North, South, East and West while making a survey in the Township in October of 1965.

Wit: 5" R. Pine S36°W 6.5'
5" J. Pine N34°W 10.7'

C-7 George H. Cannon D.S. 1854
Set post corner section 17,18,19 and 20
Wit: Tamarack 12 N60°E 43 links
Tamarack 11 S36°W 10 links

The Michigan Department of Conservation re-established this corner by single proportionate measurement between corners one mile East and one mile West while making a survey in the Township in December of 1963.

Wit: 5" Cedar N88°E 12.9'
8" Cedar S61°W 12.6'
6" Cedar N34°W 10.9'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

C-5 Found D.N.R. monument as set by the Michigan Department of Conservation while doing a survey in October of 1965.

C-7 Found D.N.R. monument as set by the Michigan Department of Conservation while doing a survey in December of 1963.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

C-5 Found D.N.R. monument
Wit: *12" Red Pine S48°W 6.74'
10" Red Pine N58°W 23.06'
10" Red Pine N14°E 15.85'
6" Red Pine S64°E 18.16'
Carsonite Post North 1'±

* Old witnesses by others

C-7 Found D.N.R. monument
Wit: *8" Cedar S86°E 13.09'
*10" Cedar S02°W 10.69'
10" Cedar S64°W 12.85'
*8" Cedar N32°W 11.10'
Carsonite Post North 1'±

*Old witnesses by others

Signed by:

Carl T. Kiiskila

Date:

2-20-02

Surveyor's Michigan License No.:

33981