

SURVEY & REMONUMENTATION
CHEBOYGAN COUNTY REMONUMENTATION CORNER

MAY 05 1997

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
CHEBOYGAN

COMMISSION

Located In:

Corner Code #

(County)

1. Public Land Survey

T 37N R 3W

M-9

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

RECEIVED
FOR RECORD
96 OCT 30 PM 12:35

James H. Granger
CLERK/REGISTER
CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, JAMES H. GRANGER

, in a field survey on SEPTEMBER 24, 1996
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as
required in the current manual of survey instructions of the United States Department of the Interior,
Bureau of Land Management or by a decree of a Court of Law and /or that the corner points
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of
Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,
recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1840 Original Survey Set wood post 10" Beech S81°W 16 lks
John Mullett 8" Sugar N71°E 7 lks
1963 Survey Metal Monument
Orlando Doyle # 7319
1968 Survey Metal Monument
Orlando Doyle # 7319
1972 Survey Found 3/4" pipe
Orlando Doyle # 7319
1986 Survey Metal Monument
Orlando Doyle # 7319
1988 LCRC Found 1" pipe
Delmer Porter # 15410
1988 LCRC Found 1" pipe
James H. Granger # 16041

1988 Survey Found 1" pipe
Delmer Porter # 15410
1988 Survey Found 1" pipe
James H. Granger # 16041
1990 Survey Found 1" pipe
James H. Granger # 16041
1994 Survey Found 1" pipe
James H. Granger # 16041
1994 Survey Found 1" pipe
Norman Quaine # 33984

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" pipe and one witness.

Monica A. Rose

LIBER 010 PAGE 188

Description of monument for corner and accessories established to perpetuate locating the position of the corner
also corner A-9, T37N, R2W

Set 5/8" x 30" rebar with Remonumentation Cap

1" Pipe			
Power Pole	N49°W	44.55'	Fd tag # 15410
SW Corner House	N51°E	111.16'	Set nail w/tag
14' Maple	N82°E	83.60'	Set nail w/tag
5" Elm	S28°E	65.14'	Set nail w/tag
GTE Riser Box	S28°E	73.18'	

Witnessed by *James H. Granger*

Surveyor's Michigan License No. 16041

Date 10-10-96

