CHEBOYGAN COUNTY REMONUMENTATION CORNER RECEIVED FOR RECORD Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			99 UEC -6 Pri 3: UI	
CHEBOYGAN (County)	Located In:	Corner Code #	Vielz Agrzynski	
1. Public Land Survey	T <u>37NR_2W</u> T R T R T R	<u>G-2</u>	CLERK/REGISTER CHEBOYGAN COUNTY MICHIGAN	
Property Controlling     in Section     Miscellaneous     Property in Sec.	S T R S T R S T R R R R R R R R R R R R		Register of Deeds Stamp & File Nur	nt
4. Lot No, Reco	rded Plat		ABCDEFGHIJK	:
5. Private Claims		·····	2 6 5 4 3 2	_
-			3 4 7 B 9 10 11	:
hereby state that under requirem lines 1 and 2 above were in con manual of survey instructions Management or by a decree of a	ments of P.A. 74, Michigan P.A.  Iformance with regulations and m  of the United States Departr  Court of Law and for that the count of the Michigan Book  ith the rules of the Michigan Book	of 1970, the corner points mention uses therefore as required in the ment of the Interior, Bureau of corner points mentioned in lines 3 and of Land Surveyors or by a Deed, found as expressed below:	oned in current 7	—1 —2 —2
NOTE: Not more than 2 cor on this certificate.	rners, all in the same town ar	nd range, may be recorded	11 31 32 33 34 35	 _;
A. Description of original n	nonument and accessories	and/or subsequent restoratio	on:	_
			<i>f</i> /	<b>3</b>
1855 GLO Resurvey Harvey Mellen	Set wood p	oost 12"W. Pine 8" Cedar	\$32°W 27 lks (OCT 7 1999)	
	Set wood p		000034 07.0-	
Harvey Mellen		8" Cedar	S32°W 27 lks OCT 7 1999  Sames A Langer  Consumentation	シーノン
Harvey Mellen  B. Description of corner e	vidence found and/or metho	8" Cedar od applied in restoring or ree	S32°W 27 lks  OCT 7 1999  James 4 Langer  Conumentation  establishing corner:	
Harvey Mellen  B. Description of corner e	vidence found and/or metho	8" Cedar od applied in restoring or ree	S32°W 27 lks OCT 7 1999  Sames A Langer  Consumentation	きしくソ
Harvey Mellen  B. Description of corner e  No original evidence fo	vidence found and/or methound. Established position b	8" Cedar od applied in restoring or ree by single proportionate measi	S32°W 27 lks  OCT 7 1999  James 4 Liver  C. Monumentation  establishing corner:  urement between G-1 and G-3.	
B. Description of corner e No original evidence for	widence found and/or methological methological methological ment for corner and access monumentation Cap inside:  N35°W 31.64' Nail N35°E 25.72' Nail S36°E 15.98' Nail	8" Cedar od applied in restoring or ree by single proportionate measi	establishing corner:  urement between G-1 and G-3.  ate localing the position of the forner:  GRANGER  PROFESSIONAL SURVEYOR  No. 16041	
B. Description of corner e No original evidence for  C. Description of monute  5/8" rebar with Rer  8" Twin Ash  5" Birch  10" Poplar  3" Poplar	ment for corner and accessement mentation Cap inside N35°W 31.64' Nail N35°E 25.72' Nail S36°E 15.98' Nail S48°W 35.04' Nail	8" Cedar od applied in restoring or ree by single proportionate meas ories established to perpetua 1" pipe & tag #16041 & tag #16041 & tag #16041	establishing corner:  urement between G-1 and G-3.  ate locality the medicing of the corner:  GRANGER PROFESSIONAL SURVEYOR No.	
B. Description of corner e No original evidence for  C. Description of monut  5/8" rebar with Rer  8" Twin Ash  5" Birch  10" Poplar	ment for corner and access monumentation Cap inside: N35°W 31.64' Nail N35°E 25.72' Nail S36°E 15.98' Nail S48°W 35.04' Nail	8" Cedar od applied in restoring or ree by single proportionate meas ories established to perpetua 1" pipe & tag #16041 & tag #16041 & tag #16041	establishing corner:  urement between G-1 and G-3.  ate localing the position of the forner:  GRANGER  PROFESSIONAL SURVEYOR  No. 16041	

MAR 0 3 2000

CECTION

FORM APPROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED 14,197. REVISED JAN., 198 REVISED OCT., 198