

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 23-26

CORNER MONUMENT Set 1" pipe with 4" alum. cap

DATE MONUMENT PLACED AND WITNESSED 4-26-67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

9" Balsam S 55 E 5.65'

5" W. Birch S 25 W 7.55'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Axle shaft in place. Locally accepted corner, occupation North, East and West. Corner is probably a perpetuation of corner set by David Bowen, County Surveyor, in 1924.

SURVEYOR'S SEAL

SIGNED \_\_\_\_\_ DATE 5-25-67  
REGISTERED LAND SURVEYOR #10068