


MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 38 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 Corner common to Sections 25-26

CORNER MONUMENT Left 3" iron pipe in place

DATE MONUMENT PLACED AND WITNESSED 5-23-67

WITNESSES TO CORNER.....



9" W. Birch N 22 W 24.3'

9" B. Spruce S 77 W 37.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a boundary survey in State Park. Probably set by Bowen in 1924 county survey.

Fits swamp edge south.

SURVEYOR'S SEAL

SIGNED Kenneth Ostling DATE 6-21-67  
REGISTERED LAND SURVEYOR #10068