

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
CHEBOYGAN  
(County)

Located In

Corner Code #

1. Public Land Survey	T	38N	R 02W	A-7
	T	38N	R 03W	M-7
2. Property Controlling in Section	S	T	R	
	S	T	R	
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

Register of Deeds Stamp & File Number

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on February 3, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

A-7– Section corner common to sec.'s 18 & 19, T38N, R02W & sec.'s 13 & 24, T38N, R03W

1996 – Remon L.C.R.C. – L.010, p.174 – James H. Granger,  
P.S.#16041 – Found 1" pipe with 4" brass cap, 2 scribed witnesses and 4" squared post.  
8" Cedar S66°E 11.29'  
14" Poplar S45°W 27.22'  
6" Birch N85°W 10.23'  
4" Balsam N12°E 16.91'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

A-7– Section corner common to sec.'s 18 & 19, T38N, R02W & sec.'s 13 & 24, T38N, R03W

Found Department of Conservation monument per Remon L.C.R.C. – L.010, p.174. Monument appeared in good condition. Found remains of 4" squared post 1' SW of monument. Accepted found DOC monument as a careful and faithful reestablishment of the position of the original corner. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7– Section corner common to sec.'s 18 & 19, T38N, R02W & sec.'s 13 & 24, T38N, R03W

4" dia. stamped brass cap on 1" Galvanized pipe

Wit: \*N04°E 16.88' to set N&T on W side 5" Balsam  
\*S63°E 11.26' to set N&T on N side 10" Cedar  
S28°W 18.11' to set N&T on SE side 2" Ash  
\*S74°W 10.14' to set N&T on S side 7" W. Birch  
Set Blue Carsonite Post 1' North

\* Witness of previous record.



Carl T. Kiiskila

3-9-11

Surveyor's Michigan License No.: 33981