

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 39 N.R. 3W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 Corner common to Sections 32 and 33

CORNER MONUMENT 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED April 25, 1961

WITNESSES TO CORNER..... 7" Cedar - S49W - 33.4 ft.



8" Elm - N18W - 15.6 ft.

18" Cedar stub - N63E - 16.7 ft.

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found by Forestry Division personnel during forest management in this area.  
Restored corner from government BTs. SW stump in place with part of face and  
marks, NE longbutt down in water but has very good face and some marks underneath.  
Corner falls in roots of 10' Elm.

SURVEYOR'S SEAL.

SIGNED Kenneth Dethling DATE April 25, 1961  
REGISTERED LAND SURVEYOR