STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

<u></u>	DeltaCOUNTY	
Υ	37 N R 24 W	-
DESCRIPTION OF CORNER 1/4 corner for sections 31/32		-
CORNER MONUMENT 1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED 6/23/69, F. J. Bray	-	-
WITNESSES TO CORNER 8" Hemlock (1/4 S) (NBT) N 50° E,	16½ links	_
N 13" W. Pine (1/4 S NBT) S 54° E, 54	. links	_
AND		<u>-</u>
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to north and to south. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR

DATE 6/26/69

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing