

# SURVEY & REMONUMENTATION

MAR 21 1997

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County  
Land Survey Remonumentation  
Peer Group Under Act 345 Of  
P.A. Of 1990 On 12/12, 1996

*Phil B. Hamling*  
Acting Chairman

For corners in  
DELTA  
(County)

Located in:

Corner Code ##

1. Public Land Survey

T 36 N R 19 W

C-11 & E-11

T      R     

T      R     

T      R     

2. Property Controlling  
in Section

S      T      R     

S      T      R     

3. Miscellaneous  
Property in Sec.

S      T      R     

S      T      R     

4. Lot No.             , Recorded Plat             

5. Private Claims

C-11 [SW COR S29] E-11 [NW COR S33]

Recorded DEC 20 1996  
at 2:00 o'clock PM  
Liber 8 Page 154  
*John C. Hansen*  
Delta County, MI Reg. of Deeds

Register of Deeds Stamp & File Number

I, M.P. DAVIS, in a field survey on NOVEMBER, 19 96,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-11 [SW COR S29] WOOD POST - A.MERRYWEATHER, D.S. - 1848 (BIRCH 30"-S70°W-30 LINKS) (MAPLE 06"-N55°E-06 LINKS)

C.E.BROTHERTON-1878-CORNER IN PLACE-NO WIT'S OR DESCRIPTION OF MONUMENT GIVEN

M.S.McNABB-1925-FOUND IRON STAKE IN ROAD "FROM PREVIOUS SURVEYS" (BIRCH 14"-N47°E-38.0')(MAPLE 16"-S38°W-34.75')

M.DAVIS-1977-FOUND 2" IRON PIPE IN PLACE-ID FROM McNABB'S MAPLE BT SW STILL GREEN-REC'D LIBER 2 OF LCR'S PG 133 (TP-S88°W-32.0')

E-11 [NW COR S33] WOOD POST-A.MERRYWEATHER, D.S.-1848 (SUGAR 12"-N34°E-21 LINKS) (BEECH 06"-S45°W-19 LINKS)

M.S.McNABB-1916-FOUND 8 SIDED IRON STAKE IN PLACE-FENCE POST BT'S SW 46' & NORTH 28.3'

J.ERICKSON-1972-SET 1/2" REBAR FROM RECORDS OF McNABB-NEW BT'S FENCE POSTS NORTH 20.0" & S45°E-43.8' (UNRECORDED)

T.OBRIEN-1978-FOUND RR SPIKE IN PLACE-NOTED FENCE POST BT'S-S41°W-36.8' S54°E-39.55' N32°W-43.65' REC'D LIBER 2 OF LCR'S PG 207

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-11 [NW COR S.29] FOUND IN PLACE 2" IRON PIPE, ID CORNER POSITION FROM McNABB'S MAPLE BT SW  
STILL GREEN. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE  
POSITION OF THE ORIGINAL CORNER.

E-11 [NW COR S33] FOUND IN PLACE AN EIGHT SIDED SOLID IRON PIN AS CALL FOR IN McNABB'S RECORDS.  
NO EVIDENCE FOUND OF O'BRIEN'S RR SPIKE. FOUND ERIKSON MONUMENT 6'N. & 3'W. OF McNABB'S COR.  
ACCEPTED EXISTING EIGHT SIDED MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION  
OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-11 SET OVER EXISTING IRON PIPE A 5/8" X 18" REBAR W/A 3 1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION & SET 6" BELOW RD GRADE.

MAPLE 30"(OLD BT)	MAPLE 08"	DRILL HOLE IN ROCK	MAPLE 14"
S38°W	N.50°W	N36°E	S22°E
35.55'	65.98'	45.30	83.70'

E-11 SET OVER EXISTING MON & 6" BELOW GRADE A 5/8" X 10" REBAR W/A 3 1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION.

SURVEY MONUMENT SIGN POST	3RD FENCE POST WEST OF COR POST	3RD FENCE POST EAST OF COR POST
NORTH	N40°W	N52°E
21.88' (TO FACE)	43.18'	37.47'

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC - DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS NOTED OTHERWISE

Signed by M.P. Davis

Date 12/10/96

Surveyor's Michigan License No. 16926

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

SEP

8 PAGE 154

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

