REMONUMENTATION

AUG 2 0 1996

LAND CORNER RECORDATION CERTIFICATE

Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On June 27, 1996

Approved By Delta County

COMMISSION	Filing Requirement	t of Act 74, Mich. P.A. 19	70 deling Chairman
For corners in DELTA		1	
(County)	Located In: C	Corner Code ##	
n D. H. Caral Organia	T 38 N R 23 W	C-6 (677)	
Public Land Survey	TR		28 June 1996
	T R		9:00 A.M. 8 Page /46
Property Controlling S	TR _TR		Walter C. Three M. of Down.
	_ T R		Celta County, Michigan
	_ T R	F	Register of Deeds Stamp & File Number
Property in Sec. S	_ T R		
4. Lot No, Recorded I	Plat		A 3 C D E F G H 1 J K L
5. Private Claims	C-7 [NW COR S20]		
C-6 [WI/4 COR SI/]	C-1 [NW COR S20]		3
			4 7 8 9 10 11 12
I, M.P. DAVIS , in a field	survey onNAY	, 19 <u>96</u> ,	5
do hereby certify that under requirements in lines 1 and 2 above were in conforma	of P.A. 74, Michigan P.A. of 1970 nce with regulations and rules), the corner points mentioned s therefore as required in the	6 13 17 16 15 14 13
current manual of survey instructions of t Management or by a decree of a Court of L	he United States Department o	of the Interior, Bureau of Land	7
above were in conformance with the rules	of the Michigan Board of Land	Surveyors or by a Decree of a	8 19 20 21 22 23 24
Court of Law; established, re-establish	red, monumented, re-monum	ented, recovered, found as	10 30 29 28 27 26 25
expressed below: NOTE: Not more than 4 corners, al	I in the same town and ran	ge, may be recorded	11
on this certificate.	THE CHE SUITE LOVE AND THE	32 , 2 ,	12 31 32 33 34 35 36
		tttt	13
A. Description of original monument C-6 [W1/4 COR S.17] WOOD POST - A.	t and accessories and/or st .MERRYWRATHER.D.S 1847 (1	ubsequent restoration: BIRCH 08"-N10"E-20 LINKS) (B	IRCH 09*-SIO°E-11 LINKS)
NO RECORD EVIDENCE OF CORNER 1			OF MICA
C-7 [NW COR S.20] WOOD POST - A.M		מאר לסענד: ממה מסבים מאר מאר מאר לסענד: ממה מסבים מה	FADACY 12*_CSS°T_20 IIN
NO RECORD EVIDENCE OF CORNER I	RECOVERY OR SUBSECUENT MONU	MENTATION	
			DAVIS LAND SURVEYO
			NO SURVEYO
			16926
			G FASS
B. Description of corner evidence for	ound and/or method applied	d in restoring or reestablishi	ing corner:
C-6 [WI/4 COR S.17] FOUND IN PLACE	I A 20" LONG IRON BOLT W/A I	1174° SQ. READ. BROKEN AND 1 SUPPOPE SEP BY LOCAL LAND SHE	N POOR CONDITION, THIS NONUMENT PARCAL VEYORS IN THE EARLY & MID 1900'S. EXISTING
MONUMENT IS LINE WITH ANCIENT	FENCE LINES TO THE NORTH A	ND SOUTH AND IS IN THE APPRO	XIMATE CENTER LINE OF THE COUNTY ROAD TO TH
			TION OF THE POSITION OF THE ORIGINAL CORNER
C-7 INW COR S.201 FOUND IN PLACE A	AND IN POOR CONDITION A 1 "	IRON PIPE AT THE APPROXIMATE	CENTER LINE INTERSECTION OF COUNTY ROADS
EAST-WEST AND SOUTH, CORNER MO	DNUMENT PLACED BY PERSON AND	D/OR PERSONS UNKNOWN. NO OTH	ER EVIDENCE OR CORNER ACCESSORIES FOUND.
ACCEPTED EXISTING MONUMENT AS	BEING THE BEST AVAILABLE EV	VIDENCE AS TO THE LOCATION O	F THE POISTION OF THE ORIGINAL CORNER.
		No.	
C. Description of monument for cor	ner and accessories establi	ished to perpetuate locating	the position of the corner:
C-6 SET OVER EXISTING MONUMENT & (5" BELOW ROAD GRADE A 5/8" :	X 18" REBAR W/A 31/4" ALUMN	CAP STAMPED TO ID THE CORNER POSITION.
			SW QUANDRANT & LARGE SNOPLOW TURNAROUND
N40°W N25°E 35.58' 39.21'	SOUTH 17.26' (TO FACE)	IN THE SE QUADRANT	
	, ,		
			CAP STAMPED TO ID THE CORNER POSITION.
CEDAR 13" CUT ON EAST END (N46°W SO8°E	OF CMP CUT ON WEST END S23°W	OF CMP SURVEY MONUMENT NORTH	oten ruot
48.02' 59.52'	60.78'	25.11' (10	FACE)
NOTE: BEARINGS TO REFERENCE OBJECT	rs are magnetic - distances		OF THE OBJECT UNLESS NOTED OTHERWISE
Signed by Mill Antuis		Date	196
Surveyor's Michigan License No.	16926		
		FORM A	APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1

8 PAGE 146