

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY.....	T. <u>38</u> N. R. <u>24</u> W.	<u>G-9, H-9</u>
2. PROPERTY CONTROLLING IN SECTION <u>27</u>	T. <u>38</u> N. R. <u>24</u> W.	<u>1</u>
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO., RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Frank J. Bray do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on May 24 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

G-9 Woodpost: Y. Birch 13 $N72^{\circ}E$ 9 links
Cedar 11 $S42^{\circ}W$ 30 links
Subsequent monument; scribed woodpost

H-9 Woodpost: Spruce 5 North 2 links
Tamarack 5 $S54^{\circ}W$ 12 links

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-9 This corner was set from notes of Marcus McLab, County Surveyor (over)

H-7 This corner was set mid-point and on a line between section corners east and west. No original evidence found.

1 This corner was set mid-point and on a line between section corner to the west and $\frac{1}{4}$ corner east.

C. Description of monument and accessories established to perpetuate locating the position of the corner:

G-9 & H-9 1" iron pipe with 4" aluminum cap. 1" 1" iron pipe

All bearings are magnetic.
G-9 3" Cedar (S22) (MBT) $N38^{\circ}E$ 1.8'
3" Cedar (lower face) (MBT) $S66^{\circ}E$ 1.8'
(Upper squared & scribed for cor. post)

H-9 9" Tamarack (4S) (MBT) South 12.8'
4" Balsam (4S) (MBT) $N72^{\circ}W$ 13.4'

1 5" Cedar (W 1/16) (BT) $N25^{\circ}W$ 5.9'
4" Cedar (W 1/16) (BT) $N58^{\circ}E$ 11.0'

SIGNED BY: _____ DATE: _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY: _____ DATE: _____

APPROVED AND SIGNED BY: Frank J. Bray DATE: 2/13/73
MICHIGAN STATE BOARD OF SURVEYORS (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 13575