SEP 1 3 1994

COMMISSION

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
Of 1990 On May 19, 199 4

Multiple Ameling

LAND CORNER RECORDATION CERTIFICATE

| For corners in | Filing Require | ment of Act 74, Mich. P.A | . 1970 |
|--|---|--|--|
| DELTA | · | 1 | · |
| (County) | Located In: | Corner Code ## | |
| ,, | | (= | |
| Public Land Survey | T 33 N R 24 W | E-2 & E-3 | 11 11 0 1004 |
| • | T R | | JUN -8 1994 |
| | T R | | Resorded |
| | T R | | 9:00 c'clock AM in Liber 8 Page 8 |
| | T R | | Viken C. Thum Pag. of Deads. |
| | T R | | Dwia County, ? fichigen |
| | T R | | Register of Deeds Stamp & File Number |
| Property in Sec. S | T R | | |
| | | | |
| 4. Lot No, Recorder | d Plat | | A B C D E F G H I J K I |
| 5. Privatę Claims | 4] E-3 [NW COR S.9] | | |
| ore furly con o. | i c-3 ink con 3.31 | | 3 1 1 1 1 1 |
| · | | _ | |
| 1, M.P. DAVIS , in a fi | ald survey on MA | V 10 Q1 | 5 7 8 9 10 11 |
| do hereby certify that under requiremen | | | od land |
| in lines 1 and 2 above were in conform | mance with regulations and | I rules therefore as required in | the ° -18-1-17-16-15-1-14-1- |
| current manual of survey instructions of | | | |
| Management or by a decree of a Court o above were in conformance with the rul | | | |
| Court of Law; established, re-established | | | |
| expressed below: | | • | 10 30 29 28 27 26 |
| NOTE: Not more than 4 corners, | all in the same town and | d range, may be recorded | 11 |
| on this certificate. | • | | 12 31 32 33 34 35 |
| | | | 13 |
| A. Description of original monume | ent and accessories and | or subsequent restoration: | |
| E-2 [W1/4 COR S.4] GEORGE ADAIR, M.S.McNABB (NO DATE) - ESTAB | | | |
| E-3 [NW COR S.9] GEORGE ADAIR,D. M.S.McNABB (NO DATE) - IDENT M.S.McNABB - 1930 - ID CORNE | IFIED FROM ORIGINAL BIRC | H BT & PIECE OF RAIL IN ROAD | (SET BT STAKES NW & SE 33') |
| B. Description of corner evidence E-2 [W1/4 COR S.4] FOUND DRAG TO FENCE LINE OCCUPATION WEST & DISTANCE SOUTH TO SECTION CO AS BEING THE BEST AVAILABLE E-3 [NW COR S.9] NO EVIDENCE OF | OTH IN PLACE APPROX 20* IN APPROX C/L OF N-S CO RNER COMPARES WELL WITH EVIDENCE AS TO THE LOCAT | M/L BELOW COUNTY ROAD SURFAC UNTY ROAD. NO EVIDENCE OF MC THE RECORDS OF MCNABB. ACCEP ION OF THE POSITION OF THE O | E AND IN LINE WITH NABB'S BT STAKES FOUND. TED EXISTING MONUMENT RIGINAL CORNER. M. P. |
| AND 17' EAST OF REMAINS OF C THE POSITION OF THE ORIGINAL | ORNER FENCE POST, ACCEPT | | |
| C. Description of monument for co | orner and accessories e | stablished to perpetuate loca | ating the position of the corner: |
| BLACK LOCUST 10" SPRUCE N44°W S37°E | 7° DRILL HOLE IN LARGE : N36°E | STONE DRILL HOLE IN LARGE WEST | CAP STAMPED TO ID THE CORNER POSITION. STONE SURVEY MONUMENT SIGN POST S57'W |
| 77.83' 49.99 | 49.88' | 27.52' | 2.12' (TO FACE) |
| | | | |
| N18°W 575°E | TAMARACK 6* SURVEY M S78°W | ONUMENT SIGN POST N65°E | TO ID THE CORNER POSITION. |
| | • | .36' (TO FACE) NCES ARE TO A NAIL IN THE CE | NTER OF THE OBJECT, UNLESS OTHERWISE NOTED. |
| Signed by Miritarii | | Date | 18/94 |
| Surveyor's Michigan License No | 16926 | | |
| | | | FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28 Revised May 14 Revised Jan. |