

✓

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
  
LAND CORNER RECORD

Delta COUNTY

T 43 N R's 22 & 23 W


T43N 24/19 T43N  
R23W 25/30 R22W

DESCRIPTION OF CORNER Section corner for Sections

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/17/71 F. J. Bray

WITNESSES TO CORNER..... 6" Cedar (S.25) (MBT) N31°W, 7.4'



6" Cedar (S.19) (MBT) N64°E, 10.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from point of an old down squared wood post. Rotted down cedar to southwest may have been original B.T. Old blazed and notched dead cedar near.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray  
REGISTERED LAND SURVEYOR  
Frank J. Bray

DATE 12-9-71

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68