

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43-44 N.R. 22W


Delta-Alger COUNTY

DESCRIPTION OF CORNER Section corner common to sections 5-6-31-32

CORNER MONUMENT 1" Pipe with 4" brass cap.

DATE MONUMENT PLACED AND WITNESSED 7-7-61 with J. Bastian, Asst. D. F.

WITNESSES TO CORNER..... 10" Cedar (S5 NBT) South 38 $\frac{1}{2}$  links



13" Hemlock (S32 NBT) N 78°E 25 links

14" W. Spruce (S31 NBT) N24°W 34 links

AND

CIRCLE CORNER REGISTERED

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two cedar BT's bearing N49°W 31 links and S48°E 11 links. Both cedars down but in fair condition. Found green Yellow Birch bearing N66°E 23 links for other B.T. Found 2" iron pipe at corner. Corner lies in East margin of swamp.

SURVEYOR'S SEAL

SIGNED \_\_\_\_\_ DATE March 13, 1962

REGISTERED LAND SURVEYOR  
Billy D. Buckler