

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 39 N.R. 28-29 W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Sections 7 and 12

CORNER MONUMENT 1" Iron Rod in Concrete Monument

DATE MONUMENT PLACED AND WITNESSED 12/60 with H.S. Peterson, D.F.

WITNESSES TO CORNER..... 15" Red Oak (1/4" MBT) N 40° W 90 Links



Corner lies 50 Links East of Road

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-witnessed as set by unknown Surveyor many years ago, probably during the early mining operations in this area. No evidence of original corner.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 2/21/61

Billy D. Buckler