

DEC 18 1995

COMMISSION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

RECORDED

NOV 21 AM 11:26

For corners in
Dickinson
(County)

Located In:

Corner Code #

- | | | | | | |
|------------------------------------|---|------------|---|------------|-----|
| 1. Public Land Survey | T | <u>39N</u> | R | <u>29W</u> | E-3 |
| | T | _____ | R | _____ | E-4 |
| | T | _____ | R | _____ | |
| | T | _____ | R | _____ | |
| 2. Property Controlling in Section | S | _____ | T | _____ | R |
| | S | _____ | T | _____ | R |
| 3. Miscellaneous | S | _____ | T | _____ | R |
| Property in Section | S | _____ | T | _____ | R |

RECEIVED BY DEEDS
CLERK
NOV 21 1995

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert F. Perkins, in a field survey on Oct. 9, 1995
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6			5		4			3		2		1
3					●								
4	7			8	●	9			10		11		12
5													
6	18			17		16			15		14		13
7													
8	19			20		21			22		23		24
9													
10	30			29		28			27		26		25
11													
12	31			32		33			34		35		36

A. Description of original monument and accessories and/or subsequent restoration:

E-3 Southeast Corner, Section 5
Post J. Mullett, D.S. 1849
Original Bearing Trees
Maple 4" S65°E 10 Lks.
Birch 6" N45°W 14 Lks.

E-4 West 1/4 Corner, Section 9
Post J. Mullett, D.S. 1849
Original Bearing Trees
Y. Pine 18" N35°W 18 Lks.
Y. Pine 3" N55°E 11 Lks.

ACCEPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON

11-30-95
ROP

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

COUNTY REPRESENTATIVE

E-3 No Evidence of Original Corner or
Assessories Found.
Located in Built-Up Residential Area.
City of Norway Land Records indicate
1 1/2" Iron Pipe for Corner witnessed to
Frame Garage.
Found Iron Pin buried 8"-Appears to be
in concrete. Checks to Garage and
Recorded Plat to West.

E-4 No Evidence of Original Corner or
Assessories Found. City
of Norway Land Corner Record (Sheet 9-J)
Indicates Axel Shaft in Section Street
as Re-established by M.S.H.D. in 1940.
Found above referenced Axel Shaft in Street
Corner Researched in 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3 Accepted above described Corner.
Placed 2 1/2" Stamped Cap over Existing Pin.
New Witnesses:
Spruce 12" S80°W (M.B.) 23.37'
Spruce 14" N62°E (M.B.) 86.24'
Power Pole #536 S87°E (M.B.) 46.35'
Guard Rail Post (E. End) S35°E (M.B.) 68.19'
S.E. Foundation-Corner of House,
N03°E (M.B.) 161.71'

E-4 Placed Monument Box over above
described Corner.
New Witnesses:
X Cut in Concrete Curb N43°W (M.B.) 36.71'
X Cut at N.W. Corner Stone Wall,
N52°E (M.B.) 58.97'.
X Cut on Lower Flange Nut F.H.,
S47°W (M.B.) 37.48'
X Cut on Concrete Fountion of House,
S53°E (M.B.) 52.95'

Signed by Robert F. Perkins

Date Nov. 7, 1995

Surveyor's Michigan License No. 12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971
REVISED MAY 14, 1976

