

DEC 18 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE NOV 22 PM 2:31
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Dickinson

(County)

Located In:

Corner Code ##

REGISTERED DEEDS
INDEXED
FILED

1. Public Land Survey

K-6 14 13

K-9 23 24

26 25

2. Property Controlling

in Section

3. Miscellaneous

Property in Sec.

T 39N R 29W
T 39N R 29W
T R
T R
S T R
S T R
S T R
S T R

K-6
K-9

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, James H. Moore, in a field survey on September 6, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-6 Post - Original Corner Set by J. H. Mullet 1849
Original Bearing Trees
8" S. Pine N45°E 7 Links
8" S. Pine S25°E 14 Links

K-9 Post - Original Corner Set by J. H. Mullet 1849
Original Bearing Trees
14" W. Pine S26°E 12 Links
14" Y. Pine N26°W 29 Links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-6 Found 5/8" Bolt Flush With Ground As Per Sundberg, Carlson's Notes
200' South of Railroad Tracks, N-S Fence Line
Record Research On File With Register of Deeds

K-9 Found 2 1/2" I.D. Iron Pipe As Per Sundberg, Carlson's Field Notes
400' North of E-W Fence Line Extended
Record Research On File With Register of Deeds

ACCEPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON
11-20-95
RJP
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-6 Set a New Dickinson County Capped Aluminum Monument Along Side 5/8" Bolt (Couldn't Remove Bolt) Monument Stamped to Identify Corner. Referenced as Follows:
7" J. Pine N59°E 61.90'
12" J. Pine S69°E 56.34'
8" J. Pine S02°W 30.74'
5" J. Pine N87°W 75.29'
Carsonite Rail S.E. 2.2'

K-9 Replaced 2 1/2" Iron Pipe With New Dickinson County Capped Aluminum Monument. Monument Stamped to Identify Corner. Referenced as Follows:
7" Triple Maple S45°E 10.75'
6" Maple S13°W 71.54'
5" Oak S71°W 55.32'
10" Maple N41°W 51.72'
Carsonite Rail North 1.0'

Signed by James H. Moore
Surveyor's Michigan License No. 28423

Date 11/20/95

