

# SURVEY & REMONUMENTATION

MAR 03 1998

RECORDED

## SECTION

LAND CORNER RECORDATION CERTIFICATE 1997 DEC 12 PM 1:37  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Dickinson</u> (County)	Located in:	Corner Code #
<u>Waucedah Township</u>		
1. Public Land Survey	T40N R28W	E-4 E-5
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

REGISTER OF DEEDS  
DICKINSON COUNTY  
IRON MOUNTAIN, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, James H. Moore, in a field survey on October 16, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-4 - 1/4 corner common to Sections 8 and 9  
Post by James H. Mullett, D.S. 1849

Hemlock 10" N60°E 12 L.  
Hemlock 6" S75°W 21 L.

E-5 - corner common to Sections 8, 9, 16 and 17  
Post by James H. Mullett, D.S. 1849

Cedar 14" S28°W 12 L.  
Spruce 12" N80°E 12 L.

ACCEPTED BY THE DICKINSON COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT  
345 OF 1990 AT A MEETING HELD ON  
12-9-97

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-4 - found 1" galvanized pipe with 4" DNR  
stamped brass cap set at an existing corner  
location by B. Buckler in 1956 (old #17)  
1956 bearing trees:

Cedar 12" S84°E 55 L.  
Cedar 12" S25°E 46 L.

E-5 - found 1" galvanized pipe with 4" DNR  
stamped brass cap set from recovered evidence  
by B. Buckler in 1956 (old #15)  
1956 bearing trees:

W. Pine 9" S89°E 7 L.  
W. Pine 12" S80°W 36 L.

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-4 - found above described monument in place  
New Witnesses:

S. Maple 6" S72°W (M.B.) 14.93' nail/tag  
S. Maple 11" S32°E (M.B.) 17.77' nail/tag  
S. Maple 6" N75°E (M.B.) 12.82' nail/tag  
S. Maple 9" N35°W (M.B.) 47.24' nail/tag

E-5 - found above described monument in place  
New Witnesses:

Cedar 14" S64°E (M.B.) 13.4' nail/tag  
Ash 6" N39°E (M.B.) 22.30' nail/tag  
S. Maple 12" S69°W (M.B.) 29.18' nail/tag  
Y. Birch 4" N53°W (M.B.) 26.32' nail/tag

placed carsonite marker North 0.80'

placed carsonite marker N45°W 0.73'

Signed by JAMES H. MOORE  
Surveyor's Michigan License No. 28423

Date 12-8-97

