

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
NORWAY TOWNSHIP		
1. Public Land Survey	T 40N R 29W	D07
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

, Jeremy J. Pipp , in a field survey on 8/06/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7.
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D07) Quarter corner common to Sections 17 and 20. 1849: James Mullett, DS. Set quarter
section post witnessed by Sugar 8 N03E 22 links (14.52'), Ironwood 8 S05W 14 links
(9.24'). 1997: Robert Perkins PS#12027 Set Dickinson County Remon Monument witnessed by 3"
Maple N38W 21.20', 3" Maple N36E 29.02', 12" Maple S68W 25.92', 6 Maple S68E 38.01'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D07) Accepted found Dickinson County Remon Monument, four NBT Witnesses (two living; two
dead and down), and carsonite post. Position is accepted as a careful and faithful
REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D07) Dickinson Co. monument
9" Maple N12E 28.16' (1/4S,NBT)
EX 7" Maple S69E 38.03' (- , -)
EX 13" Maple S72W 25.88' (- , -)
13" Maple N72W 35.74' (1/4S,NBT)
All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic.
Found carsonite post still in place North
1.5 feet.
Signed by

Surveyor's Michigan License No.

50447



August 26, 2013

For the Michigan Department of Natural Resources, Forest Resources Division