

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson
Located In:
Corner Code #
T R
T R
T R
S 35 T 40N R 29W 11
S 35 T 40N R 29W 12
S T R
S T R
S T R

Lot No. , Recorded Plat
Private Claims

9/09/2014
Jeremy J. Pipp, in a field survey on 9/09/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(11) Southwest One-Sixteenth corner of Section 35. Not set in original survey, no evidence of
subsequent establishment.

(12) Center-South One-Sixteenth corner of Section 35. Not set in original survey, no evidence of
subsequent establishment.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11) Corner position established at the intersection of the South and West One-Sixteenth lines of
Section 35.

(12) Corner position established mid-point and on-line between the Center One-Quarter corner and
the South One-Quarter corner of Section 35.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) DNR monument
8" W. Birch N58E 21.0' (1/16S,BT)
10" Maple S15E 55.0' (1/16S,BT)
11" W. Pine S27W 77.42' (1/16S,BT)
4" Maple N34W 30.12' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(12) DNR monument
7" Maple N28E 27.48' (1/16S,BT)
9" Basswood S64E 24.41' (1/16S,BT)
6" Maple S51W 16.61' (1/16S,BT)
6" Maple N60W 10.68' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Date September 10, 2014

JEREMY PIPP
PROFESSIONAL
No. 50447

20457
20458

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 and two black dots in row 12, column J.