MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_40 NR_29_F.

			DickinsonCOUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 8 & 9
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with 4" Brass cap
WIT TNESSES	то	CORNER	14" Hemlock - W 47 W - 26 Links
			12" Hard Maple - 8 52 W - 16 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Ferestry Division survey crew, while making a partial reservey of this Township. Remains of one probable B.T. still in place, hadly retted.

Corner was placed and witnessed August 5, 1954.

SURVEYORS SEAL

SIGNED CLAND SURVEYOR DATE ____