

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey

T 40N R 29W C2

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Dec 14 2000

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

(C2) Quarter corner common to Sections 5-6. Corner remonumented in 1960 and recorded in 1961 by Billy D. Buckler RLS, from two white pine stumps: 4" brass cap in concrete monument. 9" W. Spruce S63E 33 links, 9" W. Pine stub S80W 13 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C2) Recovered the 1960 monument, a 4" dia. brass cap, in good condition, appropriately stamped, set in a concrete mass, at record bearing and distance from the remaining 1960 N8T W. Spruce, now 13" dbh and in good condition. Left the monument in place and marked new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C2) Found 4" MI Dept. of Conservation
brass cap in concrete.

13" W. Spruce S64E 22.1' (1960 wit)

Blazed and scribed:

10" W. Spruce S19W 41.9' "1/4S N8T"


5" Cedar N68W 25.9' do

4" Cedar N63E 20.4' do

Sqd cedar post adjacent. Bearings are
magnetic. Distances are to notch in
lower blaze.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No: 33986

Date 1/16/01



For the Michigan Department of Natural Resources - Forest Management Division