

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

(DICKINSON COUNTY)

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 40 N. R. 30 X W.	#K-3
2. PROPERTY CONTROLLING IN SECTION	2 T. 40 N. R. 30 X W.	#14 & 16
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner K-3 (Section Corner 1, 2, 11, & 12, T40N, R30W):

Wood post (Not found. No subsequent monuments found.)
W. Pine 24 S48W 6 (Not found. No subsequent accessories found.)
W. Pine 24 N85E 11 (Found. No subsequent accessories found.)

Corner 14 (South 1/16 corner between Sections 1 & 2, T40N, R30W) and

Corner 16 (East 1/16 corner between Sections 2 & 11, T40N, R30W):

Neither of these 2 corners established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner K-3: Restored 7-16-79 from stump of original BT to NE, identified from trace of lower blaze with notch, well weathered, on the stump. Area of corner located by reference to stream crossings to E and S, swamp edge to S, marsh to W, and foot of hill to N, with which the corner position agrees substantially. No trace of second original BT.

Corner 14: Established 8-1-79 on line between Sec. Cor. 20.1725 ch. S and 1/4 cor. 20.1725 ch. N.

Corner 16: Established 8-1-79 (although mon. is stamped 7-16-79) on line between Sec. Cor. 19.989 ch. E and 1/4 cor. 19.989 ch. W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner K-3: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Red Maple 5 S26°W (mag.) 42.6 ft. "S11, NBT"
Red Maple 4 N27°W (mag.) 70.0 ft. "S 2, NBT" Declination 4° 00' West.

Corner 14: ⊕ chiselled on granite ledge.
Red Maple 7 N50°W (mag.) 23.1 ft. "1/16S, BT"
W. Pine 3 S60°W (mag.) 20.4 ft. "1/16S, BT"
Distances horizontal. Declination 3° 00' West.

Corner 16: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
W. Pine 18 N22°W (mag.) 19.6 ft. "1/16S, BT"
B. Ash 5 N 6°E (mag.) 28.7 ft. "1/16S, BT"
Declination 4° 20' West.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE March 10 1980

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

