LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

for corners in

Dickinson (County)	_ Located In:	Corner Code #				
VAUCEDAH TOWNSHIP			1			
1. Public Land Survey	ΤR					
	TR					
2. Property Controlling	S 28 T 41N R 28W	03				
n Section	S 28 T 41N R 28W S T R	05				
3. Miscellaneous	S T R					
Property in Sec.	S T R		1			
			Regi	ster of Dee	ds Stamp &	File Number
4. Lot No, Re-	corded Plat		A B	CDE	FGK	IJKLM
5. Private Claims			1	111		
	2/12/2013	3AD	2 - 6-	 - 5- -	- 4 3	 - - - -
, Jeremy J. Pipp , i	n a field survey on 2/12/2013	3AD do hereby state	3			
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2				- 910-	11-12-	
above were in conformance with regulations and rules therefore as required in the current manual of survey				 	+	
nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of			` .'	17-	16-15-	14-13-
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7						
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established			. 8 19-	20	2122_	23 24
re-established, monumented, recovered, found as expressed below:			الله			
			10-30-	70	28 27	26 25
NOTE: Not more than 2 corners, all in the same town and range, may be recorded					i i	
on this certificate.			11	32		
			12 31-		34	33 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (03) North One-Sixteenth corner common to Sections 28 and 29. Not set in original survey, no evidence of subsequent establishment.
- (05) Center-North One-Sixteenth corner of Section 28. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (03) Corner position established mid-point and on-line between the West One-Quarter corner and the Northwest corner of Section 28.
- (05) Corner position established mid-point and on-line between the Center One-Quarter corner and the North One-Quarter corner of Section 28.

/05\

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(03) DAY MOTUMETT	(05) DNK monument
6" Elm N35E 37.95' (1/16S,BT)	7" Tamarack North 15.30' (1/16S,BT)
13" Spruce S63E 42.93' (1/16S,BT)	4" Tamarack S74E 20.69' (1/16S,BT)
9" Elm S23W 19.01' (1/16S,BT)	8" Tamarack S68W 11.52' (1/16S,BT)
8" Tw. Maple N61W 34.68' (1/16S,BT)	5" Tamaraa ** ** NZ2W 15.19' (1/16S,BT)
All trees are blazed, scribed, and	All trees and fizzer, scribed, and
painted. Measurements are to nail in	painted. Measurements are to nail in
side of tree, bearings are magnetic.	side of tree bearings are magnetic.
	PIPP 100
Signed by	PROFESSIONAL July 18, 2013

Surveyor's Michigan License No.

DNP monument

DND monument

July 18, 2013

For the Michigan Department of Natural Resources,

(03)