

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF --:	(DICKINSON COUNTY) LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 41 N. R. 28 E.	C-3
2. PROPERTY CONTROLLING IN SECTION 6	T. 41 N. R. 28 E.	16
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19 , established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner C3 (Section Corner 5, 6, 7, & 8, T41N, R28W):

Cedar post	(Not found. No subsequent monuments found.)
Cedar 8 S59E 8	(Not found. No subsequent accessories found.)
Hemlock 10 N51W 39	(Not found. No subsequent accessories found.)

Corner 16 (East 1/16 corner between Sections 6 & 7, T41N, R28W):

Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner C3: Restored 9/23/77 on true line bet. Sec. Cor. 17, 18, 19, & 20, T41N, R28W and Sec. Cor. 5, 6, 31, & 32, T41-42N, R28W, at a distance from the former giving due weight to prominent natural features on the original random line as mentioned in the original field notes. Corner falls on SW side of a rock ledge, as stated in the original field notes. The corner as it falls in this survey is on a large buried rock, so probably is not the exact place as originally set.

Corner 16: Established 6/29/78 on line between Sec. Cor. 20.054 ch. E and 1/4 cor. 20.054 ch. W, and falls on a bare granite ledge.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner C3: ⦿ Chiselled in a buried rock. Set a 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap 3.00 ft. due North for a Witness Corner. NBT's are to the iron pipe W.C.
 Red Maple 6 N30°W (mag.) 26.1 ft. "S6, NBT"
 Red Maple 9 S58°E (mag.) 10.0 ft. "S8, NBT"
 Declination is 3°45' West.

Corner 16: ⦿ Chiselled in a solid granite ledge.
 W. Pine 4 N36°E (mag.) 16.6 ft. "1/16S, BT"
 R. Pine 6 S71°E (mag.) 15.1 ft. "1/16S, BT"
 Declination is 2°15' West.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE August 10, 1978

CHIEF OF SURVEY PARTY
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

