

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

(DICKINSON COUNTY)

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>41</u> N. <u>28</u> E. <u>W.</u>	<u>D-2</u>
2. PROPERTY CONTROLLING IN SECTION <u>5</u>	T. <u>41</u> N. <u>28</u> E. <u>W.</u>	<u>8</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. <u>W.</u>	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner D2 (Center of Section 5, T41N, R28W) and
Corner 8 (West 1/16 corner on E & W 1/4 line, Section 5, T41N, R28W):
Neither of these corners established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner D2: Established 6/28/78 at intersection of quarter-section lines.
Corner falls in center of a NE & SW woods road, thus monument was buried so that its top is about 6 inches below ground surface. Set a 3" x 3" x 5' squared & scribed cedar post on W side of road 9.1 ft. W of monument.

Corner 8: Established 3/13/78. As true corner falls in the W. Br. of Sturgeon R., witness monuments were placed on the true 1/4 line on both banks of river. Monument on W bank is stamped "1/16 cor. is N89-44.5E 43.3 ft." and monument on E bank is stamped "1/16 cor. is S89-44.5W 25.6 ft."

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner D2: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Cedar 15 S32 1/2° E (mag.) 20.1 ft. "1/4S, BT"

W. Spruce 11 S27° W (mag.) 50.5 ft. "1/4S, BT"
Declination is 4° 20' West.

Corner 8: Both witness monuments are 1" I.D. x 36" iron pipes with 3 3/4" aluminum cap.
Bearing trees for West W.C.:

White Spruce 14 N47° W (mag.) 89.5 ft. "WC, BT"
White Pine 36 S89 3/4° W (true) 90.4 ft. "WC, BT"

Bearing Trees for East W.C.:
Double Cedar 16 N89 3/4° E (true) 130.1 ft. "WC, BT"
Cedar 14 N46° E (mag.) 126.7 ft. "WC, BT"

Declination is 3° 30' West

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE August 13, 1978

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

