

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—	(DICKINSON COUNTY) LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 41 N. 28 R. 28 W.	B-3
2. PROPERTY CONTROLLING IN SECTION	6, T. 41 N. 28 R. 28 W.	15
3. MISCELLANEOUS PROPERTY IN SECTION	, T. N. S., R. E. W.	
4. LOT NO.	, RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner B3 (1/4 corner between Sections 6 & 7, T41N, R28W):

Hemlock post	(Not found. No subsequent monuments found.)
W. Pine 12 S21W 17	(" " " " accessories " .)
W. Pine 14 N50E 24	(" " " " " " .)

Corner 15 (West 1/16 corner between Sections 6 & 7, T41N, R28W):

Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner B3: Restored 6/29/78 proportionately on line between Sec. Cor. 40.107 ch. E and Sec. Cor. 40.859 ch. W. At this position, corner falls on a granite outcrop where no artificial monument could be set, other than a mark engraved in the rock. Th original field notes indicate a post was set, so the actual corner probably was at some other nearby place; however, could find no direct evidence of it.

Corner 15: Established 5/22/78 proportionately on line between Sec. Cor. 20.806 ch. W and 1/4 cor. 20.054 ch. E. Corner falls on W side of a stream in a small valley running NW & SE between granite ridges.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner B3:  chiselled on a kind of small plateau on S side of a rock ledge.

W. Pine 6 N46°E (mag.) 20.6 ft. "1/4S,NBT"

W. Pine 4 S85°W (mag.) 27.3 ft. "1/4S,NBT"

Declination is 0°20' West.

Corner 15: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.

B. Ash 7 S6°E (mag.) 8.5 ft. "1/16S,BT"

B. Ash 6 S83°W (mag.) 6.9 ft. "1/16S,BT"

Declination is 2°25' East

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

