## LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #								
(County) Norway Township 1. Public Land Survey	— Т R									
ŕ	TR									
2. Property Controlling	S 8 T 41N R 29W	9								
in Section	S 8 T 41N R 29W S T R	13								
3. Miscellaneous	s r R									
Property in Sec.	s r R									
• •			R	egiste	r of De	eds Sta	amp & I	File Ni	umbe	er
4. Lot No. , Re	corded Plat	,			D 12	E .	- 12	Ē J	ić.	- 4
5. Private Claims	<del></del>	*	יין נ	Ī	ŤŤ			1 7	K	LP
	6/26/2012	AD	2 =	6	╼╪╼╅	- <del> </del>	<b></b> ∳	┼─キ	+	-‡
ı, Jeremy J. Pipp , i	in a field survey on 6/26/2012	AD do hereby state	3		1 1	7		1	十	
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and					- 6 -	— <u>9</u> —	10-		-	-12-
	regulations and rules therefore as required		• —	<del>                                     </del>	+-+			++	-	
Instructions of the United States	6	<b>a</b>	-17	-16-	15-		-	-1,3		
a Court of Law and /or that the o	corner points mentioned in lines 3, 4 and 5	s above were in conformance with	7	-			<del>  </del>	+		-
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established					-20-	_21_	22	1-2	4	-24
re-established, monumented, recovered, found as expressed below:					$\bot$		2	$\bot$		
		Δ.	10		_29	28	22_			
NOTE: Not more than 2 corners, all in the same town and range, may be recorded				0.1	Ĭ.	1	100			
on this certificate.										

- A. Description of original monument and accessories and/or subsequent restoration:
- (09) Center-East One-Sixteenth corner of Section 8. Not set in original survey, no evidence of subsequent establishment.
- (13) Southeast One-Sixteenth corner of Section 8. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 8. Monument set in notched out base of Maple tree.
- (13) Corner position established at the intersection of the South and East One-Sixteenth lines of Section 8.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(09) DNR monumen	nt	(13) DNR	monument						
7" Tw. Maple NE	0.55' (1/16S,BT)	4" White Pine	N24E 26.40' (1/16S,BT)						
6" Spruce S66E 2	25.80' (1/16S,BT)	7" Cedar	\$10E 31.05' (1/16S,BT)						
5" Maple S47W 3	30.50' (1/16S,BT)	21" White Pine	\$17W 36.95' (1/16S,BT)						
6" Tri. Maple N59W 3	36.54' (1/16S,BT)	12" Cedar	N83W 35.86' (1/16S,BT)						
All trees are blazed, s	scribed, and	All trees are blazed, scribed, and							
painted. Measurements	are to nail in	painte de Measurements are to nail in							
side of tree bearings	are magnetic.	paints. Measurements are to nail in							
/ /									

Signed by

July 18, 2012

Surveyor's Michigan Ligense No.

For the Michigan Department of Natural F

GAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983

20082 20081

Rervised Oct., 1995