

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
NORWAY TOWNSHIP		
1. Public Land Survey	T 41N R 29W	E06
	T	R
	T	R
2. Property Controlling in Section	S T	R
	S T	R
	S T	R
3. Miscellaneous Property in Sec.	S T	R
	S T	R
4. Lot No. , Recorded Plat		
5. Private Claims		

, Jeremy J. Pipp , in a field survey on 4/30/2013AD do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E06) Quarter Corner common to Sections 16 and 17. 1850: John Burt, DS. Set Hemlock post witnessed by: W. Pine 24 S69W 14 links (9.24'); Hemlock 24 N78E 30 links (19.80').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E06) Found possible OBT's (W. Pine Stub & mound with Hemock knots). No marks apparent; area badly burned. Dug near record position for post to recover possible stain in soil (W. Pine Stub S73W 9.3 feet & mound with Hemock knots N80E +/-19.8 feet). Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E06) DNR monument  
8" Maple N84E 27.15' (1/4S,NBT)  
9" Maple S08E 10.77' (1/4S,NBT)  
5" Cherry S61W 25.22' (1/4S,NBT)  
5" Spruce N44W 37.21' (1/4S,NBT)

All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.

Signed by Jeremy J. Pipp  
Surveyor's Michigan License No. 50447



August 08, 2013

For the Michigan Department of Natural Resources, Forest Resources Division