## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	_ Located In:	Corner Code #						
(County) NORWAY TOWNSHIP								
Public Land Survey	T 41N R 29W T R	F12						
	† — R —							
2. Property Controlling	STR							
in Section	S 33 T 41N R 29W S T R	05						
3. Miscellaneous	S T R							
Property in Sec.	STR							
4. Lot No. , Re	corded Plat			gister of D	77 15	· · · · · ·		
5. Private Claims			1 A B	CD	E F G	HI	. J k	C L M
	10/30/2	012AD	2 6-	╼╁╾╪╾	┼╌┋╼┼	-}-		┝╌┆╼┤
, Jeremy J. Pipp , i	n a field survey on 10/30/2	012AD do hereby state	3	++		+		
	74, Michigan P.A. of 1970, the come			T P	<del>                                     </del>	-10-	—11—i	12-
	regulations and rules therefore as req							
instructions of the United States I a Court of Law and /or that the c			1,0-1	-15-	—14— 	13-		
the rules of the Michigan Board		20-		7,7	23			
'e-established, monumented, recovered, found as expressed below:						٦		
			9	29_	28	27	26	25
NOTE: Not more than 2 corr	11							
on this certificate.			1231-	32	2	_34_	35	36_
			13					Щ

- A. Description of original monument and accessories and/or subsequent restoration:
- (F12) Center One-Quarter Corner of Section 33. Not set in original survey. 1961 Michigan DNR (Billy Buckler PS#8887) set 1" I.D. with 4" Brass cap witnessed by W. Ash 8 S22W 34.5 links (22.77') "C S33, BT", Hard Maple 8 S44E 36.5 links (24.09') "BT", & Hard Maple 8 N14W 45.5 links (30.03') "BT".
- (05) Center-North One-Sixteenth corner of Section 33. Not set in original survey. 1961 Michigan DNR (Billy Buckler PS#8887) set 1" I.D. with 4" Brass cap witnessed by Hard Maple 7 S20W 26.5 links (17.49') "BT", White Birch 9 N24W 19 links (12.54') "BT", & Balsam 8 N76E 67.5 links (44.55') "BT'
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (F12) Accepted found MDNR Monument and one existing Witness. Left MDNR monument in place and rewitnessed.
- (05) Accepted found MDNR Monument and one existing Witness. Left MDNR monument in place and rewitnessed.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F12)	DNR monument	(05) DNR	monument
8" Maple	N23E 6.69' (1/4S,NBT)	8" Maple	N09E 12.37'(1/16S,NBT)
7" Maple	S25E 19.55' (1/4S,NBT)	6" Maple	N52E 23.76'(1/16S,NBT)
EX 16" ASH	S28W 22.8' ( - , - )	EX 12" Maple	\$27W 17.28' ( - , - )
7" Maple	N47W 22.68' (1/4S,NBT)	7" Maple _	N84W 10.09'(1/16S,NBT)
All trees a	re blazed, scribed, and	All totement	lazed, scribed, and
painted. M	easurements are to nail in	painted "Meas	ments are to nail in
side of tre	e, bearings are magnetic.	💌 🥱 de of tree, b	anings are magnetic.
	( ) ().	JEREMY J.	_0

Signed by

July 18, 2013

Surveyor's Michigan License No.