

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 29. W.

D i c k i n s o n COUNTY

DESCRIPTION OF CORNER 1/4 corner between Section 20 and 29

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" Soft Maple (1/4s NBT) N 78° W 52 Links

6" Soft Maple (1/4s NBT) N 30° E 28 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was re-established by setting it on line and midway between
section corners. No evidence of original corner.

Corner was placed and witnessed June 3, 1960.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 9/3/60