MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_41_ NR__29___W

		_D_i_c_k_i_n_s_o_n COUNTY
DESCRIPTION	OF CORNER	Section corner common to Sections 7.8.17.18
DESCRIPTION	OF CORNER	MONUMENT_l" Pipe with 4" Brass Cap
WITNESSES T	O CORNER .	_20" Y. Pine _ (S 18 NBT) _ S 13° W _ 15 Links
		18" W. Pine _ (S 17 NBT) _ S 83° E _ 20 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established by double proportionate measurement, section corners 1 mile to north, west and east and two miles to south.

Corner was placed and witnessed August 22, 1960.

SURVEYOR'S SEAL

SIGNED Silly D. Suckles DATE 8-29-60

REGISTERED MAND SURVEYOR

Billy D. Buckler