

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
BREEN TOWNSHIP		
1. Public Land Survey	T 42N R 27W	D06
	T R	
	T R	
2. Property Controlling in Section	S 16 T 42N R 27W	08
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

I, Jeremy J. Pipp, in a field survey on 12/18/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D06) Center One-Quarter Corner of Section 17. Not set in original survey, no evidence of subsequent establishment.

(08) Center-West One-Sixteenth corner of Section 16. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D06) Corner position established at the intersection of the North-South and East-West One-Quarter lines of Section 17.

(08) Corner position established mid-point and on-line between the Center One-Quarter corner and the West One-Quarter corner of Section 16.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D06) DNR monument
10" Cedar N20E 21.90' (1/4S,BT)
12" Spruce S74E 21.07' (1/4S,BT)
8" Cedar S05W 25.63' (1/4S,BT)
10" Maple N44W 15.11' (1/4S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resources Division

(08) DNR monument
8" Maple N79E 36.92' (1/16S,BT)
6" Maple S85E 29.03' (1/16S,BT)
8" Maple S41W 20.12' (1/16S,BT)
3" Poplar N36W 1.84' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

JEREMY J. PIPP Date July 18, 2013
PROFESSIONAL SURVEYOR



Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													