

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T...42 NR 27 W...

Dickinson

COUNTY

DESCRIPTION OF CORNER ..... 1/4 corner between sections 5 and 8

DESCRIPTION OF CORNER MONUMENT ..... 1" pipe with 4" brass cap

WITNESSES TO CORNER ..... Cedar 8" S 19 W 21 links, marked 1/4 S NBT

..... Cedar 7" N 65 E 30 1/2 links, marked 1/4 S NBT


DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner was replaced from two original cedar bearing trees. One in excellent condition and one in fair condition. Corner had been previously perpetuated by Wm C. Johnson, Dickinson County Engineer in 1936.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 14 December 1956 with Clarence Ryberg.

SURVEYORS SEAL



Henry S. Peterson

SIGNED .....  
REGISTERED LAND SURVEYOR

12/15/56

DATE .....