

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

for corners in

Dickinson	Located In:	Corner Code #
(County)		
ELCH TOWNSHIP		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling	S 11 T 42N R 28W	04
n Section	S 11 T 42N R 28W	05
	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

4. Lot No. , Recorded Plat
5. Private Claims

7/29/2013AD
Jeremy J. Pipp, in a field survey on 7/29/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(04) Northwest One-Sixteenth corner of Section 11. Not set in original survey. 1981:
Michael Beltz PS#28404 Set 5/8" Rebar with plastic cap witnessed by 4" Balsam S85E
2.88, 6" Balsam S18W 13.55', 5" Maple West 32.65', 7" ASH N32W 27.95'.

(05) Center-North One-Sixteenth corner of Section 11. Not set in original survey, no
evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(04) Accepted found capped rebar and Four witnesses (all dead) and drove MDNR Monument
over the top of existing position. Position is accepted as a careful and faithful
PERPETUATION of the position of the original corner.

(05) Corner position established mid-point and on-line between the Center One-Quarter
corner and the North One-Quarter corner of Section 11.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(04) DNR monument
8" ASH N39E 35.36' (1/16S,NBT)
5" Maple S12E 30.61' (1/16S,NBT)
4" Ironwood S61W 25.76' (1/16S,NBT)
8" Maple N31W 46.51' (1/16S,NBT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resources Division

(05) DNR monument
6" Cedar N40E 14.98' (1/16S,BT)
25" Hemlock S48E 4.42' (1/16S,BT)
16" Cedar S45W 45.18' (1/16S,BT)
21" W. Pine N82W 45.83' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Date August 26, 2013

