

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N. R. 28W


Dickinson COUNTY

DESCRIPTION OF CORNER East 1/8 corner between sections 23 and 26

CORNER MONUMENT 1" iron pipe with 4" brass cap.

DATE MONUMENT PLACED AND WITNESSED 6/1/62

WITNESSES TO CORNER..... 12" Balsam (BT)(1/8S) S63°W, 46 links



10" Spruce (BT)(1/8S) N11°W, 51½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corner and 1/4 corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE January 23, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler