

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N. R. 28 W


Dickinson COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 26, 27, 34, and 35

CORNER MONUMENT Capped 1 1/4" Iron Pipe

DATE MONUMENT PLACED AND WITNESSED 5/3/61

WITNESSES TO CORNER....10" Hard Maple (S 26 NBT) N 52° E 43 1/2 Links



6" Basswood (S 27 NBT) N 62° W 09 Links
(in clump)

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed Iron Pipe with Pipe Cap Stamped 26,27,24,25 set by
unknown party at fence corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE August 2, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler