

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

ALSO T42N-R30W M04
For corners in

Dickinson	Located In:	Corner Code #
(County)		
FELCH TOWNSHIP		
1. Public Land Survey	T 42N R 29W	A04
	T R	
	T R	
2. Property Controlling in Section	S 7 T 42N R 29W	09
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

2/07/2013AD
Jeremy J. Pipp, in a field survey on 2/25/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

4. Description of original monument and accessories and/or subsequent restoration:

(A04) Quarter corner common to Sections 7 and 12. 1846: William, Austin, & John Burt, DS. Set Sugar Post witnessed by Maple 8 S82E 14 links (9.24'), Cedar 10 N34W 33 links (22.44'). 1960: Kimberly Clark (Neal Sperhake PS#7876)[old corner report #511] set 1" I.D. with 4" Brass cap witnessed by Pine Stump 18 N65E 82 links (54.12') & Pine Stump 30 N70W 23 links (15.18'). 1997: Ewart Muller (PS#15408)[LCRC liber 2, Page 307] found Sperhake's corner and noted witnesses Balsam 4 N14E 24.5', Balsam 6 S18W 15.70', Balsam 6 S52W 11.3, 1" pipe N89E 11.58, & Carsonite Stake East 1.5 feet.

(09) Center-East One-Sixteenth corner of Section 7. Not set in original survey, no evidence of subsequent establishment.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A04) Found Kimberly Clark Monument, NOT ACCEPTED. Monument has been moved West 13.33' & North 69.69' from true position, adjacent to gate. Found Three NBT's by Muller corresponding to calculated position (note: nails had been removed from witnesses, scaring apparent on witnesses). Set MDNR Monument at calculated Position as a careful and faithful REESTABLISHMENT of the position of the original corner.

(09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 7.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A04) DNR monument
6" Spruce N27E 21.01' (1/4S,NBT)
6" Spruce N48E 10.31' (1/4S,NBT)
EX 9" Balsam S19W 15.35' (- , -)
5" Spruce S76W 8.67' (1/4S,NBT)
All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic. A carsonite rail was set North 1.5 feet.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

(09) DNR monument
12" Maple N41E 15.57' (1/16S,BT)
5" Aspen S44E 22.61' (1/16S,BT)
5" Maple S29W 32.69' (1/16S,BT)
4" Maple WEST 21.69' (1/16S,BT)
All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Date July 18, 2013
JEREMY J. PIPP
PROFESSIONAL SURVEYOR

For the Michigan Department of Natural Resources

20161

20184



Revised May 14, 1975
Revised Jan., 1983
Revised Oct., 1995