

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #
(County)		
ELCH TOWNSHIP		
Public Land Survey	T R	
	T R	
	T R	
Property Controlling	S 16 T 42N R 29W	12
Section	S 21 T 42N R 29W	04
	S T R	
Miscellaneous	S T R	
Property in Sec.	S T R	
Lot No.	Recorded Plat	
Private Claims		

6/24/2014  
Jeremy J. Pipp, in a field survey on 6/24/2014 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(12) Center-South One-Sixteenth corner of Section 16. Not set in original survey, no evidence of  
subsequent establishment.

(04) Northwest One-Sixteenth corner of Section 21. Found 3/4" rebar 3 foot high N19W 6.6 feet from  
calculated position (in place of post at intersection of Blue lines South and West).

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12) Corner position established mid-point and on-line between the Center One-Quarter corner and  
the South One-Quarter corner of Section 16.

(04) Corner position established at the intersection of the North and West One-Sixteenth lines of  
Section 21. Found 3/4" rebar 3 foot high NOT accepted.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) DNR monument  
6" Spruce N73E 5.98' (1/16S,BT)  
8" Spruce S41E 31.38' (1/16S,BT)  
8" Spruce S58W 30.02' (1/16S,BT)  
7" Spruce N70W 1.18' (1/16S,BT)

All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.

Signed by  
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resource Division

(04) DNR monument  
8" Maple N53E 28.38' (1/16S,BT)  
8" Balsam S49E 2.89' (1/16S,BT)  
12" Hemlock S55W 45.08' (1/16S,BT)  
7" Spruce S53W 5.34' (1/16S,BT)  
All trees are blazed, scribed, and  
painted. Measurements are to nail in  
side of tree, bearings are magnetic.



July 15, 2014

Register of Deeds Stamp & File Number												
A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												